




36100,36120 Vue L 36200,36220 Vue X





Assembly Instructions

Hardware



#10 x 0.625 Wood Screw



#8 x 0.625 Wood Screw




8-32 x 0.5



1/4 20 x 0.5



10-32 x 0.5



M6 x 1.0mm x 10mmL



M6 x 1.0mm x 16mmL




1/4 20 x 1.375




#10 x 1.75 Wood Screw



10-32 x 1.75



1/4 20 Snap Fastener



1/4 20 x 0.75



1/4 20 Keps Nut



10-32 Keps Nut

Tools



Screwdriver/Drill




#2 Phillips



#3 Phillips


Parts




36006




75000




36002



36003




36035/36039




Work surface



36036/36040



36038/36042




Work surface





32213/32215




Assembly Instructions





For 36100




x 4

M6 x 1.0mm x 16mmL




#3 Phillips




75000 (2)



36004 (2)




1



1

2



For 36100





x2

M6 x 1.0mm x 10mmL



#3 Phillips

1




x4

1/4 20 x 0.5





#3 Phillips

2




2



For 36120,36220

5



For 36120,36220

6

